

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                        |                            |                                |                        |
|------------------------|----------------------------|--------------------------------|------------------------|
| Intersection ID: 52432 | Main Street: ALEXA REED RD | Cross Street: CRAVEN THOMAS RD | Location: NW           |
| ADA ID: 3FFE53FBD008   | Ramp Type: Para            | Initial Pass/Fail: Fail        | Overall Compliance: No |
|                        |                            | Severity Score: 1.25           |                        |

#### Codes/Mitigation Info/Possible Solution

#### Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Entire Ramp.**

Surveyor Notes:

**N/A**

PROW/ADA:

**R304.5.3**

Total Cost:

**\$ 1600.00**

| Compliance | Description          | Data | Compliance | Description                 | Data |
|------------|----------------------|------|------------|-----------------------------|------|
| N/A        | Ramp Length LT (in)  | 45.0 | N/A        | Ramp Length RT (in)         | 57.5 |
| Yes        | Ramp Width LT (in)   | 74.0 | Yes        | Ramp Width RT (in)          | 82.0 |
| Yes        | Ramp Slope LT (%)    | 6.6  | Yes        | Ramp Slope RT (%)           | 6.4  |
| Yes        | Ramp XSlope LT (%)   | 0.8  | No         | Ramp XSlope RT (%)          | 3.0  |
| N/A        | Landing Length (in)  | N/A  | N/A        | DWS Provided?               | N/A  |
| N/A        | Landing Width (in)   | N/A  | N/A        | DWS Contrast?               | N/A  |
| N/A        | Landing Slope (%)    | N/A  | N/A        | DWS Length (in)             | N/A  |
| N/A        | Landing X Slope (%)  | N/A  | N/A        | DWS Full Width?             | N/A  |
| N/A        | Landing Curb? (Y/N)  | N/A  | N/A        | DWS Offset (in)             | N/A  |
| N/A        | Shared Landing?      | N/A  |            |                             |      |
| N/A        | Gutter Ponding?      | N/A  | N/A        | Gutter Slope (%)            | N/A  |
| N/A        | Gutter Lip Ht (in)   | N/A  | N/A        | Gutter X Slope (%)          | N/A  |
| N/A        | Painted X Walk1?     | Yes  | N/A        | Painted X Walk2?            | N/A  |
|            | X Walk 1 Direction   | To E |            | X Walk 2 Direction          | N/A  |
| N/A        | X Walk 1 Width (in)  | 99.0 | N/A        | X Walk 2 Width (in)         | N/A  |
|            | X Walk 1 Slope (%)   | 2.3  |            | X Walk 2 Slope (%)          | N/A  |
|            | X Walk 1 X Slope (%) | 0.2  |            | X Walk 2 X Slope (%)        | N/A  |
| N/A        | Ramp inside XWalk1?  | Yes  | N/A        | Ramp inside XWalk2?         | N/A  |
|            | Road Slope (%)       | N/A  | N/A        | Clear Space?                | N/A  |
|            | Road X Slope (%)     | N/A  | N/A        | Clear Space to XWalk (in)   | N/A  |
| N/A        | Any Obstructions?    | N/A  | N/A        | Storm Grate/Utility Hazard? | N/A  |
|            | Obstruction Type     |      |            | Storm Grate/Utility Type    |      |
|            |                      | N/A  |            |                             | N/A  |
|            |                      |      | Yes        | Surface Condition? (G/P)    | Good |
|            |                      |      | N/A        | Curb Slope (%)              | 20.0 |

