

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14144	Main Street: BRIAR_CREEK_RD			Cross Street: GREEN_OAKS_LN				Location:	S
ADA ID: 4006A66031CC	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance			nce: N	o Severity Score:	8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
12. 2 20 3	1 1/10/000	Remove & Replace Entire Ram	ю.	N/A	Ramp Length (in)	48.5	Yes	Ramp Slope (%)	7.7
GREE				No	Ramp Width (in)	47.5	Yes	Ramp XSlope (%)	1.1
CARRO CA	G. C.			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
and a second of the	1 mail - h			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	1 Mg 2. 2			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
3/1	100 - 1111. 50			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Part March	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
L.	- Altre	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A A A A A A A A A A A A A A A A A A A	The sale of the			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
S 1 1	A REAL			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
34 / / / / / / / / / / / / / / / / / / /	Contraction of the	1		N/A	Shared Landing?	N/A			
The Allerson		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Specific Lines		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
the all the second	A A A A A A A A A A A A A A A A A A A			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	BRIAR CREEK RD				X Walk 1 Slope (%)	2.5		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.7		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

