


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 24181	Main Street: EMSTEAD_CT	Cross Street: LANDSBURG_LN	Location: SE
ADA ID: 400744253D38	Ramp Type: PerpDiag	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 20.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		Yes	Ramp Length (in)	77.0
			No	Ramp Width (in)	64.0
			N/A	Flare Type LT	Sloped
			N/A	Flare Slope LT (%)	4.6
			N/A	Flare Traversable LT?	No
			No	Landing Length (in)	N/A
			No	Landing Width (in)	N/A
			No	Landing Slope (%)	N/A
			No	Landing X Slope (%)	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R305</p>			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	No
			No	DWS Provided?	No
			No	DWS Contrast?	No
			No	DWS Length (in)	N/A
			No	DWS Full Width?	No
			N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A
			Yes	Gutter Ponding?	No
			Yes	Gutter Lip Ht (in)	0.0
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To N
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	0.5
				X Walk 1 X Slope (%)	1.9
			N/A	Ramp inside XWalk1?	N/A
				Road Slope (%)	0.9
				Road X Slope (%)	2.2
			Yes	Any Obstructions?	No
				Obstruction Type	
Total Cost:					



Street 1 Name **EMSTEAD CT**

Stop Condition-Street 2 **StopSign**

Street 2 Name **LANDSBURG LN**

Stop Condition-Street 1 **None**

Total Cost: \$ **3200.00**

N/A

Yes

Good