

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 50102	ersection ID: 50102 Main Street: DOVE_MEADOW_DR			Cross Street: PECAN_FLATS_DR				Location:	NW	
ADA ID: 4010B3C6F2B8	DA ID: 4010B3C6F2B8 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	8.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	1 1	Possible Solutions:	Compliance Description D			Data	ata Compliance Description		Data	
	* \ /	Remove & Replace Entire Ramp		N/A	Ramp Length (in)	72.0	Yes	Ramp Slope (%)	5.0	
				No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	1.3	
Contraction of the second	> Jal	1		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
A MARINE IN THE	E CONTRACTOR			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
a state of the sta	ALCON .			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
A A A A A A A A A A A A A A A A A A A	S.			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
ta 🖌 🕹 🕹	1.16	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	and a			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
the second se	1 mar			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
a set a set of a	18.4 2			N/A	Shared Landing?	N/A				
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
A A A A A A A A A A A A A A A A A A A	11/1			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name DOVE	MEADOW DR				X Walk 1 Slope (%)	0.0		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

Yes Surface Condition? (G/P)

Good

