cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 27704	ntersection ID: 27704 Main Street: RALLY_DR Cross Street: SEALEY_CT							Location:	SW
ADA ID: 40B12BFAABA2	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	37.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data Compliance Description		Data	
		Remove & Replace Curb Ramp W	'ith	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	8.5
		Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	7.1
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	1 Marta			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
136 1966				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
22				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
6	and a state of			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	1 mm			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	CARLE IN			N/A	Shared Landing?	N/A			
1/1/201	h ing it i	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
12 4	10 16	·····,····,····,····,·····,····		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	RALLY DR	_			X Walk 1 Slope (%)	7.7		X Walk 2 Slope (%)	0.2
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	6.8
Street 2 Name	SEALEY CT			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	4.5	N/A	Clear Space?	N/A
	_				Road X Slope (%)	2.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P) Good

