


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10016842	Main Street: N_TRYON_ST	Cross Street: N/A	Location: SE
ADA ID: 40DD85579401	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: Yes
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	
Severity Score: 0			

	Possible Solutions:						
	N/A	Compliance	Description	Data	Compliance	Description	Data
		N/A	Ramp Length (in)	96.0	Yes	Ramp Slope (%)	7.0
		Yes	Ramp Width (in)	60.0	Yes	Ramp XSlope (%)	0.3
		N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
		N/A	Flare Slope LT (%)	8.0	N/A	Flare Slope RT (%)	11.6
		N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	No
		Yes	Landing Length (in)	64.0	Yes	DWS Provided?	Yes
		Yes	Landing Width (in)	62.0	Yes	DWS Contrast?	Yes
		Yes	Landing Slope (%)	0.8	Yes	DWS Length (in)	24.0
<p>Surveyor Notes:</p> <p>N/A</p>		Yes	Landing X Slope (%)	1.6	Yes	DWS Full Width?	Yes
		N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	0.0
		N/A	Shared Landing?	No			
		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.7
		Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.6
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
			X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
			X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	N/A
			X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	N/A
<p>PROW/ADA:</p> <p>N/A</p>		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
			Road Slope (%)	N/A	N/A	Clear Space?	Yes
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
			Obstruction Type			Storm Grate/Utility Type	
					N/A		N/A
					Yes	Surface Condition? (G/P)	Good
Total Cost:		\$	0.00				

