

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

		•		- /					
Intersection ID: 48393	Main St	reet: SHUFFLETOWN_DR	Cro	Cross Street: JOE_MORRISON_LN				Location:	W
ADA ID: 411EAA61EF5B Ramp Type: Perp				Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	6.	Possible Solutions:					Comp	Compliance Description	
	a la al	Remove & Replace Entire F	Ramn	N/A	Ramp Length (in)	72.0	Yes	Ramp Slope (%)	5.0
				No	Ramp Width (in)	45.0	Yes	Ramp XSlope (%)	1.5
		2		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
A BALL STOLLE	1 Variable			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Strange Internet	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	ANNOTELEFORME	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
PROW/ADA:				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
R304.5.1				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
and the state of t				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	JOE MORRISON LN	_			X Walk 1 Slope (%)	3.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 1850.0)	Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

