

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

10.7

2.3

N/A

No

N/A

0.3

2.3

N/A

N/A

N/A

N/A

N/A

Good

To NE

Main Street: BALLANTYNE\_COMMONS\_PY Cross Street: ESSEX\_FELLS\_DR Intersection ID: 27277 Location: NW **Overall Compliance: No Severity Score:** 22.5 ADA ID: 415AE5EA4D9F Ramp Type: PerpDiag Initial Pass/Fail: Fail

**Codes/Mitigation Info/Possible Solution** 

None

StopSign

## Field Measurements/Component Compliance



**BALLANTYNE COMMONS PY** Street 1 Name Stop Condition-Street 2 **ESSEX FELLS DR** Street 2 Name Stop Condition-Street 1

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA

Not Found, R304.5.1, R304.2.2, R304.5.3

Compliance Description Data Compliance Description No N/A Ramp Length (in) 62.0 Ramp Slope (%) No Ramp XSlope (%) No Ramp Width (in) 46.0 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A Flare Slope RT (%) Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A DWS Provided? Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A Landing Slope (%) DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A Painted X Walk1? No N/A Painted X Walk2? X Walk 1 Direction To S X Walk 2 Direction N/A N/A X Walk 2 Width (in) X Walk 1 Width (in) X Walk 1 Slope (%) 2.8 X Walk 2 Slope (%) X Walk 1 X Slope (%) 1.9 X Walk 2 X Slope (%) N/A N/A N/A Ramp inside XWalk2? Ramp inside XWalk1? Road Slope (%) 0.8 N/A Clear Space? N/A Road X Slope (%) 0.8 Clear Space to XWalk (in) N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? **Obstruction Type** Storm Grate/Utility Type

N/A

Yes

Surface Condition? (G/P)





Total Cost:



3200.00