

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 49309 Main Street: NATIONS_FORD_RD Cross Street: PANGLE_DR Location: ADA ID: 41972DE84F4F Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score:	SE 12.5
ADA ID: 41972DE84F4F Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score:	12.5
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance	
Possible Solutions: Compliance Description Data Compliance Description	Data
Remove & Replace Curb Ramp With N/A Ramp Length (in) 48.0 Yes Ramp Slope (%)	6.2
Two New Directional Ramps or Yes Ramp Width (in) 48.0 No Ramp XSlope (%)	5.5
Equivalent. N/A Flare Type LT N/A N/A Flare Type RT	N/A
N/A Flare Slope LT (%) N/A Flare Slope RT (%)	N/A
N/A Flare Traversable LT? N/A N/A Flare Traversable RT?	N/A
N/A Landing Length (in) N/A DWS Provided?	N/A
Surveyor Notes: N/A Landing Width (in) N/A N/A DWS Contrast?	N/A
Surveyor Notes: N/A Landing Width (in) N/A N/A DWS Contrast? N/A Landing Slope (%) N/A N/A DWS Length (in) N/A Landing X Slope (%) N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A DWS Offset (in)	N/A
N/A Landing X Slope (%) N/A N/A DWS Full Width?	N/A
N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in)	N/A
N/A Shared Landing? N/A	
PROW/ADA: N/A Gutter Ponding? N/A N/A Gutter Slope (%)	N/A
R304.5.3 N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%)	N/A
N/A Painted X Walk1? No N/A Painted X Walk2?	No
X Walk 1 Direction To N X Walk 2 Direction	To W
N/A X Walk 1 Width (in) N/A N/A X Walk 2 Width (in)	N/A
Street 1 Name PANGLE DR X Walk 1 Slope (%) 0.2 X Walk 2 Slope (%)	5.1
Stop Condition-Street 2 StopSign X Walk 1 X Slope (%) 5.5 X Walk 2 X Slope (%)	2.0
Street 2 Name NATIONS FORD RD N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2?	N/A
Stop Condition-Street 1 None Road Slope (%) 4.0 N/A Clear Space?	N/A
Road X Slope (%) 4.3 N/A Clear Space to XWalk (in)	N/A
N/A Any Obstructions? N/A N/A Storm Grate/Utility Hazard?	N/A
Total Cost: \$ 3200.00 Obstruction Type Storm Grate/Utility Type	
N/A	N/A

Yes Surface Condition? (G/P)

Good

