cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13627	Main Street: COMMONWEALTH_AV			Cross Street: WESTOVER_ST				Location:	N	
ADA ID: 41B3ADF348F3	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: N				o Severity Score:	8.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description			Data Compliance Description			
IT the bar is	18 per	Remove & Replace Entire Ramp).	N/A	Ramp Length (in)	67.0	Yes	Ramp Slope (%)	5.7	
TRACE BALL	8/			No	Ramp Width (in)	47.5	Yes	Ramp XSlope (%)	1.4	
July Marshall I have a second	11 . 1	7		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
16V U115	11821	2		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
A B S				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
S STONE S		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
ALTER AL	1-1-	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		1		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
I A BALL	a shart	6		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
6				N/A	Shared Landing?	N/A				
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
1 SP and my	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
· Shart Street the sect				X Walk 1 Direction	To SE		X Walk 2 Direction	N/A		
	4		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
Street 1 Name WES	STOVER ST	_			X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.3		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

Yes Surface Condition? (G/P)

Good

