

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11444Main Street: ALLEGHANY_STCross Street: MCKINLEY_DRLocation:NEADA ID: 41B5D4F640ACRamp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 21.25

Codes/Mitigation Info/Possible Solution



| Street 1 Name | MCKINLEY DR |
|-------------------------|-------------|
| Stop Condition-Street 2 | StopSign |
| Street 2 Name | N/A |
| Stop Condition-Street 1 | N/A |

| Possible Solutions: | | | | |
|-------------------------------|--|--|--|--|
| Remove & Replace Entire Ramp. | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| Surveyor Notes: | | | | |
| N/A | | | | |
| | | | | |
| | | | | |
| PROW/ADA: | | | | |
| | | | | |
| Not Found, R304.5.1, R304.2.2 | | | | |
| | | | | |
| | | | | |
| • | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

| | | 2 5 | |
|--|---|-----|--|
| | 1 | | |



Total Cost:



1850.00

| Field Measurements/Component Compliance | | | | | | | | |
|-----------------------------------------|-----------------------|-------|------|-----------------------------|------|--|--|--|
| Compliance Description Data | | Data | Comp | liance Description | Data | | | |
| N/A | Ramp Length (in) | 71.5 | No | Ramp Slope (%) | 10.3 | | | |
| No | Ramp Width (in) | 44.0 | Yes | Ramp XSlope (%) | 1.3 | | | |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | | | |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | | | |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | | | |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | | | |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | | | |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | | | |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | | | |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | | | |
| N/A | Shared Landing? | N/A | | | | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | | | |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | | | |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A | | | |
| | X Walk 1 Direction | To SW | | X Walk 2 Direction | N/A | | | |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | | | |
| | X Walk 1 Slope (%) | 1.2 | | X Walk 2 Slope (%) | N/A | | | |
| | X Walk 1 X Slope (%) | 2.3 | | X Walk 2 X Slope (%) | N/A | | | |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | | | |
| | Road Slope (%) | N/A | N/A | Clear Space? | N/A | | | |
| | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A | | | |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | | | |
| | Obstruction Type | | | Storm Grate/Utility Type | | | | |
| | | N/A | | | N/A | | | |
| | | | Yes | Surface Condition? (G/P) | Good | | | |