

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 22011	Main Street: SOUTH_BV				HILL_RD	Location:	SW		
ADA ID: 41C971C65CA8	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No					12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Possible Solutions:								liance Description	Data
		Remove & Replace Entire Ram	D .	N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	9.1
			-	Yes	Ramp Width (in)	60.0	Yes	Ramp XSlope (%)	1.0
文文 月月 人》 月 232				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	1 Bas			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	1 4			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	HILL PD			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	E.	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	. S. Martin A			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	A COM			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
THE A CALL	12 10-	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	18 DITE			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
11 X Paline L				X Walk 1 Direction	To SE		X Walk 2 Direction	N/A	
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	SOUTH BV				X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

