


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | |
|------------------------|---------------------------------|----------------------------------|------------------------|
| Intersection ID: 46745 | Main Street: CUMBERLAND COVE DR | Cross Street: NORMANS LANDING DR | Location: SE |
| ADA ID: 41D97DF022DC | Ramp Type: PerpDiag | Initial Pass/Fail: Fail | Overall Compliance: No |
| | | Severity Score: 47.5 | |

| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | |
|--|---|--|---|-----------------------------|-------------|
|  | Possible Solutions: | | Compliance | Description | Data |
| | Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. | | No | Ramp Length (in) | 49.0 |
| | | | No | Ramp Width (in) | 26.0 |
| | | | N/A | Flare Type LT | N/A |
| | | | N/A | Flare Slope LT (%) | N/A |
| | | | N/A | Flare Traversable LT? | N/A |
| | | | N/A | Landing Length (in) | N/A |
| | | | N/A | Landing Width (in) | N/A |
| | | | N/A | Landing Slope (%) | N/A |
| | | | N/A | Landing X Slope (%) | N/A |
| <p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.5.1, R304.2.2</p> | | | N/A | Flare Type RT | N/A |
| | | | N/A | Flare Slope RT (%) | N/A |
| | | | N/A | Flare Traversable RT? | N/A |
| | | | N/A | DWS Provided? | N/A |
| | | | N/A | DWS Contrast? | N/A |
| | | | N/A | DWS Length (in) | N/A |
| | | | N/A | DWS Full Width? | N/A |
| | | | N/A | DWS Offset (in) | N/A |
| | | | N/A | Gutter Ponding? | N/A |
| | | | N/A | Gutter Lip Ht (in) | N/A |
| <p>Total Cost:</p> <p>\$ 3200.00</p> | | | No | Painted X Walk1? | No |
| | | | To N | X Walk 2 Direction | To W |
| | | | N/A | X Walk 2 Width (in) | N/A |
| | | | 4.3 | X Walk 2 Slope (%) | 6.1 |
| | | | 3.0 | X Walk 2 X Slope (%) | 2.4 |
| | | | N/A | Ramp inside XWalk2? | N/A |
| | | | 1.4 | Clear Space? | N/A |
| | | | 9.3 | Clear Space to XWalk (in) | N/A |
| | | | N/A | Storm Grate/Utility Hazard? | N/A |
| | | | N/A | Storm Grate/Utility Type | N/A |
| | | | N/A | Surface Condition? (G/P) | Good |

