


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 44850	Main Street: STEELE_CREEK_RD	Cross Street: SHOPTON_RD_WEST	Location: SW
ADA ID: 422DF1A6FCB5	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 22.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance													
	Possible Solutions:		Compliance			Description			Data	Compliance			Description			Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)		71.0		No	Ramp Slope (%)		10.0					
			No	Ramp Width (in)		40.0		No	Ramp XSlope (%)		3.7					
			N/A	Flare Type LT		N/A		N/A	Flare Type RT		N/A					
			N/A	Flare Slope LT (%)		N/A		N/A	Flare Slope RT (%)		N/A					
			N/A	Flare Traversable LT?		N/A		N/A	Flare Traversable RT?		N/A					
			N/A	Landing Length (in)		N/A		N/A	DWS Provided?		N/A					
			N/A	Landing Width (in)		N/A		N/A	DWS Contrast?		N/A					
			N/A	Landing Slope (%)		N/A		N/A	DWS Length (in)		N/A					
			N/A	Landing X Slope (%)		N/A		N/A	DWS Full Width?		N/A					
Surveyor Notes:		N/A	N/A	Landing Curb? (Y/N)		N/A		N/A	DWS Offset (in)		N/A					
			N/A	Shared Landing?		N/A										
PROW/ADA:		R304.5.1, R304.2.2, R304.5.3	N/A	Gutter Ponding?		N/A		N/A	Gutter Slope (%)		N/A					
			N/A	Gutter Lip Ht (in)		N/A		N/A	Gutter X Slope (%)		N/A					
			N/A	Painted X Walk1?		Yes		N/A	Painted X Walk2?		N/A					
				X Walk 1 Direction		To N			X Walk 2 Direction		N/A					
			N/A	X Walk 1 Width (in)		108.0		N/A	X Walk 2 Width (in)		N/A					
				X Walk 1 Slope (%)		2.6			X Walk 2 Slope (%)		N/A					
				X Walk 1 X Slope (%)		3.0			X Walk 2 X Slope (%)		N/A					
Street 1 Name		SHOPTON RD WEST	N/A	Ramp inside XWalk1?		Yes		N/A	Ramp inside XWalk2?		N/A					
Stop Condition-Street 2		Signal		Road Slope (%)		N/A		N/A	Clear Space?		N/A					
Street 2 Name		N/A		Road X Slope (%)		N/A		N/A	Clear Space to XWalk (in)		N/A					
Stop Condition-Street 1		N/A		Any Obstructions?		N/A		N/A	Storm Grate/Utility Hazard?		N/A					
				Obstruction Type					Storm Grate/Utility Type							
								N/A			N/A					
								Yes	Surface Condition? (G/P)		Good					
Total Cost:		\$ 1850.00														

