

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                                         |                              |                                         |                        |
|-----------------------------------------|------------------------------|-----------------------------------------|------------------------|
| Intersection ID: 52915                  | Main Street: WILLOW_GREEN_PL | Cross Street: WOODWARD_AV               | Location: NW           |
| ADA ID: 4245FC2D5198                    | Ramp Type: Directional1      | Initial Pass/Fail: Pass                 | Overall Compliance: No |
| Severity Score: 0                       |                              |                                         |                        |
| Codes/Mitigation Info/Possible Solution |                              | Field Measurements/Component Compliance |                        |



Possible Solutions:

**Remove & Replace Entire Ramp.**

Surveyor Notes:

**N/A**

PROW/ADA:

**R304.5.3, R305.2**

| Compliance | Description           | Data  | Compliance | Description                 | Data |
|------------|-----------------------|-------|------------|-----------------------------|------|
| N/A        | Ramp Length (in)      | 94.5  | Yes        | Grade Break?                | Yes  |
| Yes        | Ramp Width (in)       | 67.0  | No         | Grade Break Slope (%)       | 8.6  |
| Yes        | Ramp Slope (%)        | 8.1   | Yes        | Grade Break XSlope (%)      | 0.7  |
| Yes        | Ramp XSlope (%)       | 1.3   |            |                             |      |
| Yes        | Flare Type LT         | N/A   | Yes        | Flare Type RT               | N/A  |
| N/A        | Flare Slope LT (%)    | N/A   | N/A        | Flare Slope RT (%)          | N/A  |
| N/A        | Flare Traversable LT? | No    | N/A        | Flare Traversable RT?       | No   |
| Yes        | Landing Length (in)   | 120.0 | Yes        | DWS Provided?               | Yes  |
| Yes        | Landing Width (in)    | 68.5  | Yes        | DWS Contrast?               | Yes  |
| Yes        | Landing Slope (%)     | 0.8   | Yes        | DWS Length (in)             | 24.0 |
| Yes        | Landing X Slope (%)   | 1.2   | Yes        | DWS Full Width?             | Yes  |
| N/A        | Landing Curb? (Y/N)   | N/A   | No         | DWS Offset LT (in)          | 3.5  |
| N/A        | Shared Landing?       | No    | Yes        | DWS Offset RT (in)          | 4.0  |
| Yes        | Gutter Ponding?       | No    | Yes        | Gutter Slope (%)            | 3.3  |
| Yes        | Gutter Lip Ht (in)    | 0.0   | Yes        | Gutter X Slope (%)          | 0.8  |
| N/A        | Painted X Walk1?      | No    |            | Road Slope (%)              | 3.9  |
|            | X Walk 1 Direction    | To E  |            | Road X Slope (%)            | 1.3  |
|            | X Walk 1 Width (in)   | N/A   |            | Clear Space?                | Yes  |
|            | X Walk 1 Slope (%)    | 3.9   | N/A        | Clear Space to XWalk (in)   | N/A  |
|            | X Walk 1 X Slope (%)  | 1.3   | Yes        | Storm Grate/Utility Hazard? | No   |
| N/A        | Ramp inside XWalk1?   | N/A   |            | Storm Grate/Utility Type    |      |
| Yes        | Any Obstructions?     | No    |            |                             | N/A  |
|            | Obstruction Type      |       | Yes        | Surface Condition? (G/P)    | Good |
|            |                       |       | N/A        | Curb Slope (%)              | 1.7  |

Total Cost: \$ 1600.00

