

Access Compliance Report Public Rights-of-Way (Curb Ramps)



\cdot									
Intersection ID: N/A	Main Street: YORK_CENTER			Street:	N/A	Location:	SW		
ADA ID: 427246A2186E	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:					Compliance Description Data		
		Remove & Replace Entire Ramp	_	N/A	Ramp Length (in)	39.0	No	Ramp Slope (%)	8.8
			•	Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.1
	And the second			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
A	ANT NO			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
5 6 B				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	And the second second			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
· · · · · · · ·	C. Cardina	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Miles / the man	States -	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	V N			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
and the second	YAN I	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
013/1 26 4	1.5.5 1	Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	LIL.				X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE				X Walk 1 Slope (%)	2.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	2.8		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

