## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 5924 Main Street: GUM_BRANCH_RD					Street:	WOODLYNN_DR	Location:	NW		
ADA ID: 4272C692C0EF	Ramp Type: Combination1				Initial Pass/Fail: Fail Overall Compliance				o Severity Score:	1.25
Cod	les/Mitigation Info	/Possible Solution				Field Measurer	nents/C	ompo	nent Compliance	
in steam to supply the	Possible Solutions:			Compliance Description			Data Compliance Description			
		Remove & Replace Entir	re Rar	mp.	N/A	Ramp Length LT (in)	26.0	N/A	Ramp Length RT (in)	18.0
the second second		Remove & Replace Side			Yes	Ramp Width LT (in)	72.0	Yes	Ramp Width RT (in)	70.0
		_			Yes	Ramp Slope LT (%)	5.1	Yes	Ramp Slope RT (%)	1.9
	1/0				No	Ramp XSlope LT (%)	4.3	No	Ramp XSlope RT (%)	2.4
					N/A	Ramp Length (in)	28.0	Yes	Ramp Slope (%)	2.0
	- Plant			Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.4	
		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
ि स्ति <mark>हि</mark>		RP & RT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
CUM_BRANCH_RD 8					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Contractor					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
A DELEMANT COMPANY OF THE REAL PROPERTY OF					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	Martin Contraction	Not Found, R304.5.3			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	*			N/A	Shared Landing?	N/A				
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	StopSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	WOODLYNN DR				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A					X Walk 1 Direction	To E		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	N/A
						X Walk 1 X Slope (%)	1.9		X Walk 2 X Slope (%)	N/A
		Total Cost:	\$	2200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	N/A		Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			) 0					N/A	Any Obstruction?	N/A
	Carlos Carlos			1 Salt					Obstruction Type	
				<b>Constant</b>						N/A
7 7						The second second		N/A	Storm Grate/Utility Hazard?	N/A
	the second se				Section and the section of the secti	A CONTRACTOR OF			o. o	

Yes Surface Condition? (G/P) Good Curb Slope (%) 12.0





