cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Good

· · · ·								
Intersection ID: 10019678 Mai	10019678 Main Street: ANDOVER_RD		Cross Street: N/A				SW	
ADA ID: 428B63A6A8CE Rar	Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance			o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
E ADDOVER RD	Possible Solutions:	Com	liance Description Data		Compliance Description		Data	
	Remove & Replace Curb Ramp W	/ith N/A	Ramp Length (in)	35.0	No	Ramp Slope (%)	9.3	
	Two New Directional Ramps or Equivalent.	Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.3	
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	-E	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	e N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
		N/A	Shared Landing?	N/A				
	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.2.2	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
			X Walk 1 Direction	To E		X Walk 2 Direction	To N	
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	N/A		X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	0.2	
Stop Condition-Street 2	one		X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	2.1	
Street 2 Name ANDOVER	RD	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1 Stop	Sign		Road Slope (%)	0.3	N/A	Clear Space?	N/A	
			Road X Slope (%)	4.5	N/A	Clear Space to XWalk (in)	N/A	
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 32	200.00	Obstruction Type			Storm Grate/Utility Type		
				N/A			N/A	

Yes Surface Condition? (G/P)

