

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 17555 Main Street: E_WOODLAWN_RD Cross Street: OLD_PINEVILLE_RD Location: NW **Overall Compliance: No** ADA ID: 42AA90353E73 Ramp Type: Para Initial Pass/Fail: Fail **Severity Score:** 25

Codes/Mitigation Info/Possible Solution



OLD PINEVILLE RD Street 1 Name Stop Condition-Street 1 Signal Street 2 Name N/A Stop Condition-Street 2 N/A

CCCIDIC CCIALICII	
Possible Solutions:	Con
Remove & Replace Entire Ramp.	N/A
•	Yes
	Yes
	Yes
	N/A
	N/A
Surveyor Notes:	N/A
LT RP < 5%	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
R304.3.2	N/A
	N/A
	N/A

Total Cost: 1600.00

Field Measurements/Component Compliance							
Compliance Description		Data	Comp	liance Description	Data		
N/A	Ramp Length LT (in)	68.0	N/A	Ramp Length RT (in)	48.0		
Yes	Ramp Width LT (in)	71.0	Yes	Ramp Width RT (in)	71.0		
Yes	Ramp Slope LT (%)	1.6	No	Ramp Slope RT (%)	13.9		
Yes	Ramp XSlope LT (%)	0.4	Yes	Ramp XSlope RT (%)	0.2		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To E		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	2.5		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		
			N/A	Curb Slope (%)	9.1		
47							





