


Access Compliance Report

Public Rights-of-Way (Curb Ramps)

Intersection ID: 52450		Main Street: TRANQUIL_OAK_PL		Cross Street: MOSS_LN		Location: NW							
ADA ID: 42AAC7DBB106		Ramp Type: Directional1		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 12.5					
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance									
 <div>Street 1 NameMOSS LN</div> <div>Stop Condition-Street 1StopSign</div> <div>Street 2 NameN/A</div> <div>Stop Condition-Street 2N/A</div>				Possible Solutions:		Compliance		Description		Data			
				Remove & Replace Entire Ramp.		N/A		Ramp Length (in)		65.0		N/A	
						Yes		Ramp Width (in)		67.0		N/A	
						No		Ramp Slope (%)		9.1		N/A	
						Yes		Ramp XSlope (%)		0.4			
						N/A		Flare Type LT		N/A		N/A	
						N/A		Flare Slope LT (%)		N/A		N/A	
						N/A		Flare Traversable LT?		N/A		N/A	
						N/A		Landing Length (in)		0.0		N/A	
						N/A		Landing Width (in)		0.0		N/A	
<div>Surveyor Notes:</div> <div>N/A</div> <div>PROW/ADA:</div> <div>R304.2.2</div>						N/A		Landing Slope (%)		0.0			
						N/A		Landing X Slope (%)		0.0		N/A	
						N/A		Landing Curb? (Y/N)		N/A		N/A	
						N/A		Shared Landing?		N/A		N/A	
						N/A		Gutter Ponding?		0.0		N/A	
						N/A		Gutter Lip Ht (in)		0.0		N/A	
						N/A		Painted X Walk1?		No			
								X Walk 1 Direction		To S			
								X Walk 1 Width (in)		N/A			
								X Walk 1 Slope (%)		2.9		N/A	
						X Walk 1 X Slope (%)		4.4		N/A			
				N/A		Ramp inside XWalk1?		N/A					
				N/A		Any Obstructions?		N/A		N/A			
						Obstruction Type		Yes		Surface Condition? (G/P)			
								N/A		N/A			
										Curb Slope (%)			
										2.2			
				Total Cost:		\$		1600.00					

