

Access Compliance Report

Public Rights-of-Way (Curb Ramps)

Intersection ID: 5481	Main Street: MCCLURE_CR	Cross Street: PLEASANT_GROVE_RD	Location:	E
ADA ID: 42AFDE0DD3E3	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score: 10

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Detectable
Warning System. Grind Gutter Lip.**

Surveyor Notes:

**NO CURB. DWS OS MEASURED TO
ASP**

PROW/ADA:

R305.1.4, R305.2, R302.7.2

Total Cost: \$ 1000.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	76.0	Yes	Grade Break?	Yes
Yes	Ramp Width (in)	64.0	Yes	Grade Break Slope (%)	2.6
Yes	Ramp Slope (%)	1.2	Yes	Grade Break XSlope (%)	0.2
Yes	Ramp XSlope (%)	0.6			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Yes	Landing Length (in)	74.5	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	66.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	1.5	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	0.5	No	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	No	No	DWS Offset LT (in)	30.0
N/A	Shared Landing?	No	No	DWS Offset RT (in)	101.1
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	4.0
No	Gutter Lip Ht (in)	0.3	Yes	Gutter X Slope (%)	1.3
N/A	Painted X Walk1?	No		Road Slope (%)	1.6
	X Walk 1 Direction	To W		Road X Slope (%)	2.8
	X Walk 1 Width (in)	N/A		Clear Space?	Yes
	X Walk 1 Slope (%)	1.6	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	2.8	Yes	Storm Grate/Utility Hazard?	No
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	N/A

Street 1 Name	MCCLURE CR
Stop Condition-Street 1	None
Street 2 Name	N/A
Stop Condition-Street 2	N/A

