

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 21586	586 Main Street: FAWNBROOK_LN			Cross	Street:	W_ARROWOOD_RD	Location:	NW		
ADA ID: 42C4B1D780DD	Ramp Type: BlendTrans2			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	33.75
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:			Compliance Description		Data Compliance		liance Description	Data
the state of the state		Remove & Replace Curb Ramp Two New Directional Ramps or Equivalent.	Ram	p With	N/A	Ramp Length (in)	50.0	Yes	BlendTrans Slope (%)	2.4
A A A A A A A A A A A A A A A A A A A			Ramps or		No	Ramp Width (in)	39.0	No	BlendTrans XSlope (%)	7.7
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	1 The second			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
A CARA S	X	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
b b b		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	R304.5.1, R304.5.3			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
Here I and	•				X Walk 1 Direction	To S		X Walk 2 Direction	To SE	
						X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name WARI	ROWOOD RD	-				X Walk 1 Slope (%)	1.5		X Walk 2 Slope (%)	2.3
Stop Condition-Street 1	None					X Walk 1 X Slope (%)	3.3		X Walk 2 X Slope (%)	3.6
Street 2 Name FAW	NBROOK LN				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign					Road Slope (%)	6.0		Clear Space?	N/A
	-					Road X Slope (%)	3.6	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A







Yes

N/A

Surface Condition? (G/P)

Curb Slope (%)

Good

4.4