

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10617 Main Street: STATE_ST **Cross Street: WHITEHAVEN AV** Location: NE ADA ID: 4305738F21CA Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 36.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



WHITEHAVEN A Street 1 Name Stop Condition-Street 2 StopSig Street 2 Name STATE S Stop Condition-Street 1 Non

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

DA:

ound, R304.5.1, R304.5.3

人はらばく	PROW/AD
V	
jn	
T	
ne	
	Total Coats

Total Cost: 3200.00

Comp	liance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	64.0	Yes	Ramp	Slope (%)	5.2
No	Ramp Width (in)	24.0	No	Ramp	XSlope (%)	2.6
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	No
	X Walk 1 Direction	To W		X Wa	lk 2 Direction	To S
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	8.1		X Wa	lk 2 Slope (%)	3.5
	X Walk 1 X Slope (%)	4.6		X Wa	lk 2 X Slope (%)	5.0
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
	Road Slope (%)	4.2	N/A	Clear	Space?	N/A
	Road X Slope (%)	6.6	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm	n Grate/Utility Hazard?	N/A
	Obstruction Type			Storm	n Grate/Utility Type	
		N/A				N/A
			Yes	Surfa	ce Condition? (G/P)	Good





