

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

58.0

51.0

0.3

5.7

5.9

2.1

N/A

N/A

N/A

N/A

N/A

20.1

Intersection ID: 7355 Main Street: HIDDEN FOREST DR **Cross Street: PONDELLA DR** Location: SW Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: 43340B2C50B4 Ramp Type: Combination1 **Severity Score:** 47.5

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

N/A

No

Yes

No

N/A

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A N/A

N/A

N/A

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

No

Yes

No

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

Curb Slope (%)

Flare Traversable RT?

Ramp XSlope RT (%)

Data

59.0

31.5

2.6

5.0

31.0

39.0

N/A

N/A

N/A

N/A

N/A



Street 1 Name StopSign **PONDELLA DR** Stop Condition-Street 1 N/A Street 2 Name Stop Condition-Street 2 N/A Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: LT RP < 5%, RT RP < 5% PROW/ADA: Not Found, R304.5.1, R304.5.1, R304.5.3



Total Cost:



1800.00

	• , ,				
	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	Shared Landing?	N/A			
	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To S		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	4.7		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	8.0		X Walk 2 X Slope (%)	N/A
	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A
			Obstruction Type		
					N/A
		N/A	Storm Grate/Utility Hazard?	N/A	
			Storm Grate/Utility Type		
			l		N/A
			Yes	Surface Condition? (G/P)	Good