

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10023411	0023411 Main Street: CHOATE_CR				N/A	Location:	SW			
ADA ID: 434C55745285	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No					12.5	
			miniari	· · · ·						
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance Compliance Description Data						
		Possible Solutions:		Compliance Description			Data Compliance Description			
		Remove & Replace Entire Ram	o.	N/A	Ramp Length (in)	86.0	N/A	Grade Break?	N/A	
				Yes	Ramp Width (in)	72.0	N/A	Grade Break Slope (%)	0.0	
				No	Ramp Slope (%)	8.5	N/A	Grade Break XSlope (%)	0.0	
	A STREET WAL			Yes	Ramp XSlope (%)	0.7				
	and the second second			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
CHOATE_OR			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0		
C Participation and the second	1.01	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
the second se	the start	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
	2 . W.			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
	C Zage The			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
THE MAN WELL				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
	A SACTORINATION	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
		R304.2.2		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
to the water and the	New March			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No		Road Slope (%)	4.1	
Street 1 Name	ENTRANCE				X Walk 1 Direction	To NE		Road X Slope (%)	0.4	
Stop Condition-Street 1	None				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	4.1	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	0.4	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	7.4	

