


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 17851		Main Street: SCALEYBARK_RD		Cross Street: BROOKRUN_DR		Location:		SW									
ADA ID: 43A690187775		Ramp Type: Directional2		Initial Pass/Fail: Pass		Overall Compliance: No		Severity Score: 2.5									
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance													
				Possible Solutions:		Compliance		Description		Data		Compliance		Description		Data	
				Remove & Replace Entire Ramp.		N/A		Ramp Length (in)		141.0		Yes		Grade Break?		Yes	
						Yes		Ramp Width (in)		51.0		No		Grade Break Slope (%)		5.1	
						Yes		Ramp Slope (%)		7.0		Yes		Grade Break XSlope (%)		2.4	
						Yes		Ramp XSlope (%)		0.2							
						N/A		Flare Type LT		N/A		N/A		Flare Type RT		N/A	
						N/A		Flare Slope LT (%)		N/A		N/A		Flare Slope RT (%)		N/A	
						N/A		Flare Traversable LT?		N/A		N/A		Flare Traversable RT?		N/A	
						Yes		Landing Length (in)		48.0		Yes		DWS Provided?		Yes	
						Yes		Landing Width (in)		60.0		Yes		DWS Contrast?		Yes	
Surveyor Notes:				N/A		Yes		Landing Slope (%)		0.2		Yes		DWS Length (in)		24.0	
						Yes		Landing X Slope (%)		0.3		No		DWS Full Width?		No	
PROW/ADA:				Not Found, R304.5.3, R305.1.4, R305.2		N/A		Landing Curb? (Y/N)		N/A		Yes		DWS Offset LT (in)		0.0	
						N/A		Shared Landing?		No		No		DWS Offset RT (in)		103.0	
						Yes		Gutter Ponding?		No		Yes		Gutter Slope (%)		4.3	
						Yes		Gutter Lip Ht (in)		0.0		Yes		Gutter X Slope (%)		4.1	
						N/A		Painted X Walk1?		No				Road Slope (%)		1.4	
Street 1 Name				BROOKRUN DR				X Walk 1 Direction		To NW				Road X Slope (%)		6.4	
Stop Condition-Street 1				None				X Walk 1 Width (in)		N/A				Clear Space?		Yes	
Street 2 Name				N/A				X Walk 1 Slope (%)		1.4		N/A		Clear Space to XWalk (in)		N/A	
Stop Condition-Street 2				N/A				X Walk 1 X Slope (%)		6.4		Yes		Storm Grate/Utility Hazard?		No	
						N/A		Ramp inside XWalk1?		N/A				Storm Grate/Utility Type			
						Yes		Any Obstructions?		No						N/A	
								Obstruction Type				Yes		Surface Condition? (G/P)		Good	
										N/A		No		Curb Slope (%)		16.1	
Total Cost:				\$		1800.00											

