

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 15074	Main Street: MAGNOLIA_AV	Cross Street: PARK_RD	Location: NE
ADA ID: 43C10248F23D	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 17.5	

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R304.5.2, R305.1.4, R302.7.2

Total Cost: \$ 1600.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	102.0	No	Grade Break?	No
Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	3.0
Yes	Ramp Slope (%)	5.5	N/A	Grade Break XSlope (%)	1.7
Yes	Ramp XSlope (%)	1.2			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
Yes	Flare Slope LT (%)	9.5	Yes	Flare Slope RT (%)	9.5
N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
Yes	Landing Length (in)	48.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	53.0	Yes	DWS Contrast?	Yes
No	Landing Slope (%)	2.2	Yes	DWS Length (in)	24.5
No	Landing X Slope (%)	3.6	No	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	N/A	Yes	DWS Offset LT (in)	3.5
N/A	Shared Landing?	No	Yes	DWS Offset RT (in)	2.0
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.5
No	Gutter Lip Ht (in)	1.5	Yes	Gutter X Slope (%)	0.6
N/A	Painted X Walk1?	No		Road Slope (%)	2.4
	X Walk 1 Direction	To SW		Road X Slope (%)	0.6
	X Walk 1 Width (in)	N/A		Clear Space?	Yes
	X Walk 1 Slope (%)	2.4	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	0.6	Yes	Storm Grate/Utility Hazard?	No
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	13.0

Street 1 Name	PARK RD
Stop Condition-Street 1	None
Street 2 Name	N/A
Stop Condition-Street 2	N/A

