

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

Intersection ID: 10034513 Main Street: PINEVILLE-MATTHEWS RD Cross Street: N/A Location: NW Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: 43DD9E08880C Ramp Type: PerpDiag Severity Score: 21.25

Compliance Description

**Codes/Mitigation Info/Possible Solution** 

None

Field Measurements/Component Compliance

Compliance Description

Data



PINEVILLE-MATTHEWS RD Street 1 Name Stop Condition-Street 2 **ENTRANCE** Street 2 Name Stop Condition-Street 1 StopSign Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.2.2

Total Cost: 3200.00

No Ramp Slope (%) N/A Ramp Length (in) 58.5 8.7 Yes Ramp XSlope (%) No Ramp Width (in) 42.0 0.6 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To SE X Walk 2 Direction To NE N/A N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) X Walk 1 Slope (%) 4.3 X Walk 2 Slope (%) 1.3 X Walk 1 X Slope (%) 0.1 X Walk 2 X Slope (%) 3.1 N/A N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? Road Slope (%) 2.7 N/A Clear Space? N/A N/A Road X Slope (%) 3.5 Clear Space to XWalk (in) N/A N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good





