

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 19337 Main Street: PARK_RD Cross Street: SELWYN_AV Location: NW

ADA ID: 44227FCDA2DC Ramp Type: PerpDiag Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 35.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
SELWYN AV
Stop Condition-Street 2
Signal
Street 2 Name
PARK RD
Stop Condition-Street 1
Signal

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Restripe Crosswalk(s) To Provide Clear space. Remove & Replace Gutter.

Surveyor Notes:

Possible Solutions:

N/A

PROW/ADA:

Not Found, R304.5.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R305, R302.7.2

Comp	oliance Description	Data	Comp	liance Description	Data
N/A	Ramp Length (in)	40.0	Yes	Ramp Slope (%)	5.4
Yes	Ramp Width (in)	61.0	No	Ramp XSlope (%)	4.2
N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	2.2	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	N/A
No	Landing Length (in)	N/A	No	DWS Provided?	No
No	Landing Width (in)	N/A	N/A	DWS Contrast?	No
No	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
No	Landing X Slope (%)	N/A	N/A	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.3
No	Gutter Lip Ht (in)	1.0	No	Gutter X Slope (%)	4.4
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
	X Walk 1 Direction	To S		X Walk 2 Direction	To E
N/A	X Walk 1 Width (in)	86.0	N/A	X Walk 2 Width (in)	86.0
	X Walk 1 Slope (%)	0.4		X Walk 2 Slope (%)	5.3
	X Walk 1 X Slope (%)	6.7		X Walk 2 X Slope (%)	1.1
Yes	Ramp inside XWalk1?	Yes	Yes	Ramp inside XWalk2?	Yes
	Road Slope (%)	4.1	N/A	Clear Space?	No
	Road X Slope (%)	4.7	No	Clear Space to XWalk (in)	94.0
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			1		

Yes

Surface Condition? (G/P)

Good





Total Cost:



4450.00