cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

10.5

Intersection ID: 10032864	ersection ID: 10032864 Main Street: NATIONS_FORD_RD				Street:	N/A	Location:	Е		
ADA ID: 445804E1136F					Initial Pass/Fail: Fail Overall Compliance: No					
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					10.110	
STADAN DIS	1	Possible Solutions:							Data	
5. Du		Remove & Replace Entire	e Ram	ι ρ.	N/A	Ramp Length LT (in)	78.0	N/A	Ramp Length RT (in)	71.0
A A A A A A A A A A A A A A A A A A A					Yes	Ramp Width LT (in)	64.0	Yes	Ramp Width RT (in)	64.0
E I I I	1. 2 5				No	Ramp Slope LT (%)	9.4	Yes	Ramp Slope RT (%)	6.3
	And The second				No	Ramp XSlope LT (%)	2.2	Yes	Ramp XSlope RT (%)	0.4
	the all				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		Surveyor Notes:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	E	N/A			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	LEIBERT DE	4			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	The R	4			N/A	Shared Landing?	N/A			
- Friend - I	4			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	5	PROW/ADA:			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
C C C C C C C C C C C C C C C C C C C		R304.3.2, R304.5.3			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
		,,				X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
E.				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
S ALL ALL ALL ALL ALL ALL ALL ALL ALL AL	4				X Walk 1 Slope (%)	3.0		X Walk 2 Slope (%)	N/A	
Street 1 Name	NATIONS FORD RD	,				X Walk 1 X Slope (%)	0.1		X Walk 2 X Slope (%)	N/A
Stop Condition-Street 1	None				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Street 2 Name	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
Stop Condition-Street 2	N/A					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	17.5				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
1					N/A	Obstruction Type	N/A	IN/A	•	IN/ <i>I</i> A
		T-1-1-0	•	1000.00		Obstruction Type	NI/A		Storm Grate/Utility Type	
1		Total Cost:	\$	1600.00			N/A			N/A
								Yes	Surface Condition? (G/P)	Good

