

# Access Compliance Report


## Public Rights-of-Way

### (Curb Ramps)

|                        |                        |                            |                        |
|------------------------|------------------------|----------------------------|------------------------|
| Intersection ID: 14093 | Main Street: E_4TH_ST  | Cross Street: HAWTHORNE_LN | Location: S            |
| ADA ID: 453D60DE0F91   | Ramp Type: BlendTrans1 | Initial Pass/Fail: Fail    | Overall Compliance: No |
|                        |                        |                            | Severity Score: 21.25  |

#### Codes/Mitigation Info/Possible Solution

#### Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.**

Surveyor Notes:

**N/A**

PROW/ADA:

**Not Found, R304.5.1, R304.5.3**

Total Cost: \$ 3200.00

| Compliance | Description           | Data  | Compliance | Description                 | Data  |
|------------|-----------------------|-------|------------|-----------------------------|-------|
| N/A        | Ramp Length (in)      | 86.0  | Yes        | BlendTrans Slope (%)        | 3.4   |
| No         | Ramp Width (in)       | 44.0  | No         | BlendTrans XSlope (%)       | 6.0   |
| N/A        | Flare Type LT         | N/A   | N/A        | Flare Type RT               | N/A   |
| N/A        | Flare Slope LT (%)    | N/A   | N/A        | Flare Slope RT (%)          | N/A   |
| N/A        | Flare Traversable LT? | N/A   | N/A        | Flare Traversable RT?       | N/A   |
| N/A        | Landing Length (in)   | N/A   | N/A        | DWS Provided?               | N/A   |
| N/A        | Landing Width (in)    | N/A   | N/A        | DWS Contrast?               | N/A   |
| N/A        | Landing Slope (%)     | N/A   | N/A        | DWS Length (in)             | N/A   |
| N/A        | Landing X Slope (%)   | N/A   | N/A        | DWS Full Width?             | N/A   |
| N/A        | Landing Curb? (Y/N)   | N/A   | N/A        | DWS Offset (in)             | N/A   |
| N/A        | Shared Landing?       | N/A   |            |                             |       |
| N/A        | Gutter Ponding?       | N/A   | N/A        | Gutter Slope (%)            | N/A   |
| N/A        | Gutter Lip Ht (in)    | 1.0   | N/A        | Gutter X Slope (%)          | N/A   |
| N/A        | Painted X Walk1?      | Yes   | N/A        | Painted X Walk2?            | Yes   |
|            | X Walk 1 Direction    | To NE |            | X Walk 2 Direction          | To NW |
|            | X Walk 1 Width (in)   | 112.0 |            | X Walk 2 Width (in)         | 110.0 |
|            | X Walk 1 Slope (%)    | 3.8   |            | X Walk 2 Slope (%)          | 1.9   |
|            | X Walk 1 X Slope (%)  | 1.2   |            | X Walk 2 X Slope (%)        | 3.2   |
| N/A        | Ramp inside XWalk1?   | Yes   | N/A        | Ramp inside XWalk2?         | Yes   |
|            | Road Slope (%)        | 3.7   |            | Clear Space?                | N/A   |
|            | Road X Slope (%)      | 1.7   | N/A        | Clear Space to XWalk (in)   | N/A   |
| N/A        | Any Obstructions?     | N/A   | N/A        | Storm Grate/Utility Hazard? | N/A   |
|            | Obstruction Type      |       |            | Storm Grate/Utility Type    |       |
|            |                       | N/A   |            |                             | N/A   |
|            |                       |       | Yes        | Surface Condition? (G/P)    | Good  |
|            |                       |       | No         | Curb Slope (%)              | 11.2  |

Street 1 Name E 4TH ST  
 Stop Condition-Street 1 Signal  
 Street 2 Name HAWTHORNE LN  
 Stop Condition-Street 2 Signal

