


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 12802	Main Street: PECAN_AV	Cross Street: SCHOOL_ST	Location: SE
ADA ID: 4589D2724494	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
Severity Score: 33.75			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:				
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.				
	Surveyor Notes:				
	N/A				
	PROW/ADA:				
	Not Found, R304.5.1, R304.2.2				
		Compliance	Description	Data	Compliance
		N/A	Ramp Length (in)	60.0	No
		No	Ramp Width (in)	40.0	Yes
		N/A	Flare Type LT	N/A	N/A
<p>Street 1 Name</p> <p>Stop Condition-Street 2</p> <p>Street 2 Name</p> <p>Stop Condition-Street 1</p>		N/A	Flare Slope LT (%)	N/A	N/A
		N/A	Flare Traversable LT?	N/A	N/A
		N/A	Landing Length (in)	N/A	N/A
		N/A	Landing Width (in)	N/A	N/A
		N/A	Landing Slope (%)	N/A	N/A
		N/A	Landing X Slope (%)	N/A	N/A
		N/A	Landing Curb? (Y/N)	N/A	N/A
		N/A	Shared Landing?	N/A	
		N/A	Gutter Ponding?	Yes	N/A
		N/A	Gutter Lip Ht (in)	N/A	N/A
<p>Total Cost:</p> <p>\$ 3200.00</p>		N/A	Painted X Walk1?	No	N/A
			X Walk 1 Direction	To N	
		N/A	X Walk 1 Width (in)	N/A	N/A
			X Walk 1 Slope (%)	3.4	
			X Walk 1 X Slope (%)	1.4	
		N/A	Ramp inside XWalk1?	N/A	N/A
			Road Slope (%)	0.7	N/A
			Road X Slope (%)	1.8	N/A
		N/A	Any Obstructions?	N/A	N/A
			Obstruction Type		
				N/A	N/A
				Yes	Surface Condition? (G/P)
					Good

