cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 48133 Main Street: WHISTLER'S_CHASE_DR				eet:	ACORN_CREEK_LN	Location:	SW			
ADA ID: 45EAC6171CDB Ramp Type: PerpDiag			nitial Pass/Fail: Fail Overall Compliance: No				Severity Score:	10		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	C to	Possible Solutions:	C	Compliance Description			Data Compliance Description		Data	
A 11 A		Remove & Replace Curb Ramp W	ith N	I/A	Ramp Length (in)	47.5	Yes	Ramp Slope (%)	6.6	
		Two New Directional Ramps or		lo	Ramp Width (in)	43.0	No	Ramp XSlope (%)	2.2	
		Equivalent.	N	/ A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
			Ν	I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	and the second s		N	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.			Ν	I/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:	Ν	I/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A	Ν	I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
			N	I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
			Ν	I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			Ν	I/A	Shared Landing?	N/A				
		PROW/ADA:		I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		Not Found R304 5 1 R304 5 3	Ν	/ A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
			N	I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
					X Walk 1 Direction	To E		X Walk 2 Direction	To N	
			N	I/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name WHISTL	LER'S CHASE DR	-			X Walk 1 Slope (%)	2.5		X Walk 2 Slope (%)	5.0	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	4.7		X Walk 2 X Slope (%)	0.2	
Street 2 Name AC	CORN CREEK LN		N	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	None				Road Slope (%)	3.4	N/A	Clear Space?	N/A	
					Road X Slope (%)	3.6	N/A	Clear Space to XWalk (in)	N/A	
			Ν	I/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 32	00.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

es Surface Condition? (G/P) Good

