

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 21238 Main Street: CAROSAN LN **Cross Street: SARDIS LN** Location: NE **Overall Compliance: No** ADA ID: 463E44366B64 Ramp Type: Directional1 Initial Pass/Fail: Fail **Severity Score:** 1.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



CAROSAN LN Street 1 Name Stop Condition-Street 1 StopSign Street 2 Name N/A Stop Condition-Street 2 N/A

Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: R304.5.3

N/ Ye Ye No N/ N/ N/ N/ N/ N/ N/ N/

Comp	liance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	129.0	N/A	Grade	e Break?	N/A
Yes	Ramp Width (in)	70.0	N/A	Grade	e Break Slope (%)	0.0
Yes	Ramp Slope (%)	2.2	N/A	Grade	e Break XSlope (%)	0.0
No	Ramp XSlope (%)	3.1				
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	0.0
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	0.0	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	0.0	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	0.0	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	0.0	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset LT (in)	N/A
N/A	Shared Landing?	N/A	N/A	DWS	Offset RT (in)	N/A
N/A	Gutter Ponding?	0.0	N/A	Gutte	r Slope (%)	N/A
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutte	r X Slope (%)	N/A
N/A	Painted X Walk1?	No		Road	Slope (%)	5.3
	X Walk 1 Direction	To SW		Road	X Slope (%)	0.3
	X Walk 1 Width (in)	N/A	l	Clear	Space?	N/A
	X Walk 1 Slope (%)	5.3	N/A	Clear	Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	0.3	N/A	Storm	Grate/Utility Hazard?	N/A
N/A	Ramp inside XWalk1?	N/A		Storm	Grate/Utility Type	
N/A	Any Obstructions?	N/A				N/A
	Obstruction Type		Yes	Surfa	ce Condition? (G/P)	Good
		N/A	N/A	Curb	Slope (%)	0.1





Total Cost:



1600.00