cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



					0 1	MONTEITH DD	1			
Intersection ID: 7556	Main Street: GEORGETOWN_DR			Cross Street: MONTEITH_DR					Location:	NW
ADA ID: 46A68021DD7C	Ramp Type: Perp			Initial	Initial Pass/Fail: Fail Overall Compliance: N				o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description			Data Compliance Description			
	A star	Remove & Replace En	tire Ramp).	N/A	Ramp Length (in)	29.0	Yes	Ramp Slope (%)	5.1
States - 1 total	and a second		•		No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	3.5
A TABLE IN THE TO	The second				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
The line of		1			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	1				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	the part				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
EU EU	1				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
CEOLICE	Photo A				N/A	Shared Landing?	N/A			
	1200	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	W C	Not Found, R304.5.1,	R304.5.3		N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A
	1861				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
A DECEMBER OF					X Walk 1 Direction	To S		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name GEORG	ETOWN DR	_				X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	2.7		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						•••	N/A			N/A

s Surface Condition? (G/P) Good

