

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 4263 Main Street: DAVIS LAKE PY Cross Street: SNOWS ENTRY PL Location: **Overall Compliance: No ADA ID: 46E36356FFAD** Ramp Type: Directional1 Initial Pass/Fail: Fail Severity Score: 61.25

## **Codes/Mitigation Info/Possible Solution** Field Measurements/Component Compliance Possible Solutions: Compliance Description Data Compliance Description Data N/A Grade Break? N/A Ramp Length (in) 43.0 N/A Remove & Replace Entire Ramp. N/A No Ramp Width (in) 44.0 Grade Break Slope (%) 0.0 N/A No Ramp Slope (%) 10.7 Grade Break XSlope (%) 0.0 Ramp XSlope (%) 10.1 No N/A Flare Type LT N/A N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) 0.0 Surveyor Notes: N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A 0.0 N/A **DWS Provided?** N/A Landing Length (in) N/A N/A Landing Width (in) 0.0 N/A **DWS Contrast?** N/A Ł N/A Landing Slope (%) 0.0 N/A DWS Length (in) N/A N/A N/A Landing X Slope (%) 0.0 DWS Full Width? N/A PROW/ADA: N/A Landing Curb? (Y/N) N/A N/A DWS Offset LT (in) N/A R304.5.1, R304.2.2, R304.5.3, R302.7 N/A Shared Landing? N/A N/A DWS Offset RT (in) N/A N/A **Gutter Ponding?** 0.0 N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) 0.0 N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No Road Slope (%) 7.5 **SNOWS ENTRY PL** To NW Street 1 Name X Walk 1 Direction Road X Slope (%) 5.8 Stop Condition-Street 1 StopSign X Walk 1 Width (in) N/A Clear Space? N/A N/A 7.5 N/A N/A Street 2 Name X Walk 1 Slope (%) Clear Space to XWalk (in) Stop Condition-Street 2 N/A X Walk 1 X Slope (%) 5.8 N/A Storm Grate/Utility Hazard? N/A N/A Ramp inside XWalk1? N/A Storm Grate/Utility Type N/A N/A Any Obstructions? N/A Total Cost: **Obstruction Type** No Surface Condition? (G/P) 1600.00 Poor







N/A N/A

Curb Slope (%)

N/A