

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16649 Main Street: CHURCHILL DOWNS CT Cross Street: WALKER_RD Location: **Overall Compliance: No** ADA ID: 46FC0F55B7D7 Ramp Type: PerpDiag Initial Pass/Fail: Fail Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

None **WALKER RD**

None

Field Measurements/Component Compliance



CHURCHILL DOWNS CT Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1

Remove & Replace Curb Ramp With **Two New Directional Ramps or** Equivalent.

Surveyor Notes:

N/A

	WA	
The same of the sa	PROW/ADA:	
	R304.2.2, R304.5.3	
	Total Cost:	\$ 3200 00

Iotal Cost:

Comp	liance Description	Data	Comp	liance Description	Data
N/A	Ramp Length (in)	50.0	No	Ramp Slope (%)	11.0
Yes	Ramp Width (in)	51.0	No	Ramp XSlope (%)	3.4
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To NW		X Walk 2 Direction	To W
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	4.5
	X Walk 1 X Slope (%)	3.7		X Walk 2 X Slope (%)	2.6
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	2.1	N/A	Clear Space?	N/A
	Road X Slope (%)	3.4	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good





