## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15220	Main Str	reet: ARDSLEY_RD	Cross S	Street:	HERMITAGE_RD	Location:	NW		
ADA ID: 473A837A4C7B	Ramp Ty	Ramp Type: PerpDiag			nitial Pass/Fail: Fail Overall Compliance: No				13.75
Codes/Mitigation Info/Possible Solution				itial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75 Field Measurements/Component Compliance					
A W MARKE		Possible Solutions:					liance Description	Data	
it.		Remove & Replace Curb Ramp W	/ith	N/A	Ramp Length (in)	110.0	No	Ramp Slope (%)	8.8
		Two New Directional Ramps or	-	Yes	Ramp Width (in)	60.0	No	Ramp XSlope (%)	3.1
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A A A				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	Nº Carl Star	····,···		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					X Walk 1 Direction	To S		X Walk 2 Direction	To NE
And I have	18 Brancester			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ARDSLEY RD	_			X Walk 1 Slope (%)	7.0		X Walk 2 Slope (%)	2.6
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	2.3		X Walk 2 X Slope (%)	6.9
Street 2 Name	HERMITAGE RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	3.6	N/A	Clear Space?	N/A
					Road X Slope (%)	4.6	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

