

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| | | | | - | | | | | |
|---|--|-----------------------------|---------|--|-----------------------|-----------|------------------------|-----------------------------|------|
| Intersection ID: 10036745 | Main Street: S_GRAHAM_ST | | | s Street: | N/A | Location: | NW | | |
| ADA ID: 474E5C710D63 | Ramp Type: Directional1 | | | Initial Pass/Fail: Fail Overall Compliance: No | | | | o Severity Score: | 12.5 |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | |
| AN AL AND AND A | | Possible Solutions: | | Compliance Description Data | | | Compliance Description | | Data |
| | | Remove & Replace Entire Ran | ιр. | N/A | Ramp Length (in) | 50.0 | N/A | Grade Break? | N/A |
| | | | • | Yes | Ramp Width (in) | 70.0 | N/A | Grade Break Slope (%) | 0.0 |
| | | | | Yes | Ramp Slope (%) | 6.3 | N/A | Grade Break XSlope (%) | 0.0 |
| The second se | | | | No | Ramp XSlope (%) | 6.5 | | | |
| ALL THE ALL OF THE ALL | 1 8 | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| A | 1 4 | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | 0.0 |
| | and the second s | Surveyor Notes: | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| E S | | N/A | | N/A | Landing Length (in) | 0.0 | N/A | DWS Provided? | N/A |
| B B | | | | N/A | Landing Width (in) | 0.0 | N/A | DWS Contrast? | N/A |
| 01 | | | | N/A | Landing Slope (%) | 0.0 | N/A | DWS Length (in) | N/A |
| the second second | - | | | N/A | Landing X Slope (%) | 0.0 | N/A | DWS Full Width? | N/A |
| A CARLEN AND | | PROW/ADA: | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset LT (in) | N/A |
| | N | R304.5.3 | | N/A | Shared Landing? | N/A | N/A | DWS Offset RT (in) | N/A |
| | | | | N/A | Gutter Ponding? | 0.0 | N/A | Gutter Slope (%) | N/A |
| | | | | N/A | Gutter Lip Ht (in) | 0.0 | N/A | Gutter X Slope (%) | N/A |
| | | | | N/A | Painted X Walk1? | No | | Road Slope (%) | 1.5 |
| Street 1 Name | ENTRANCE | | | | X Walk 1 Direction | To SW | | Road X Slope (%) | 3.0 |
| Stop Condition-Street 1 | StopSign | | | | X Walk 1 Width (in) | N/A | | Clear Space? | N/A |
| Street 2 Name | N/A | | | | X Walk 1 Slope (%) | 1.5 | N/A | Clear Space to XWalk (in) | N/A |
| Stop Condition-Street 2 | N/A | | | | X Walk 1 X Slope (%) | 3.0 | N/A | Storm Grate/Utility Hazard? | N/A |
| | | | | N/A | Ramp inside XWalk1? | N/A | | Storm Grate/Utility Type | |
| | | | | N/A | Any Obstructions? | N/A | | | N/A |
| | | Total Cost: \$ | 1600.00 | | Obstruction Type | | Yes | Surface Condition? (G/P) | Good |
| | | | | | | N/A | N/A | Curb Slope (%) | 3.0 |

