

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9929 Main Street: HERRIN_AV **Cross Street: CARD ST** Location: NE **Overall Compliance: No** Ramp Type: PerpDiag Initial Pass/Fail: Pass Severity Score: 19.25 ADA ID: 474FD7600159

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



HERRIN AV Street 1 Name Stop Condition-Street 2 None Street 2 Name **CARD ST** Stop Condition-Street 1 StopSign Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes: **NO RT SW**

PROW/ADA:

Not Found, R304.5.3, R304.2.1, R305.2, R302.7.2

Total Cost: 3200.00

Comp	oliance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	25.0	Yes	Ramp	Slope (%)	7.6
Yes	Ramp Width (in)	48.0	No	Ramp	XSlope (%)	2.1
N/A	Flare Type LT	Sloped	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	2.5	N/A	Flare	Slope RT (%)	7.2
N/A	Flare Traversable LT?	Yes	N/A	Flare	Traversable RT?	No
No	Landing Length (in)	33.0	Yes	DWS	Provided?	Yes
No	Landing Width (in)	45.0	Yes	DWS	Contrast?	Yes
Yes	Landing Slope (%)	1.7	Yes	DWS	Length (in)	24.5
Yes	Landing X Slope (%)	1.9	Yes	DWS	Full Width?	Yes
N/A	Landing Curb? (Y/N)	No	No	DWS	Offset (in)	2.5
N/A	Shared Landing?	No				
Yes	Gutter Ponding?	No	Yes	Gutte	Slope (%)	2.0
No	Gutter Lip Ht (in)	1.0	Yes	Gutte	X Slope (%)	0.4
N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	No
	X Walk 1 Direction	To W		X Wal	k 2 Direction	To S
N/A	X Walk 1 Width (in)	N/A	N/A	X Wal	k 2 Width (in)	N/A
	X Walk 1 Slope (%)	4.8		X Wal	k 2 Slope (%)	1.3
	X Walk 1 X Slope (%)	1.9		X Wal	k 2 X Slope (%)	0.4
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
	Road Slope (%)	2.1	N/A	Clear	Space?	Yes
	Road X Slope (%)	5.7	N/A	Clear	Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm	Grate/Utility Hazard?	No
	Obstruction Type			Storm	Grate/Utility Type	
		N/A				N/A

Yes

Surface Condition? (G/P)

Good





