cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: BALLANTYNE_COMMONS_PKW0Moss Street: N/A Location: E									
ADA ID: 47A00D8B3710 Ramp Type: PerpDiag			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	Possible Solutions:		Compliance Description			Data Compliance Description		Data	
	Remove & Replace Curb Ramp W	/ith	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	11.1	
	Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.3	
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
A CONTRACT OF A CONTRACT. CONTRACT OF A CONTRACT. CONTRACT OF A CONTRACT. CONTRACT OF A CONTRACT. CONTRACT OF A CONTRACT. CONTRACT OF A CONTRACT OF A CONTRACT OF A CONTRACT. CONTRACT OF A CONTRACT OF A CONTRACT. CONTRACT OF A CONTRACT OF A CONTRACT OF A CONTRACT. CONTRACT OF A CONTRACT. CONTRACTACT OF			N/A	Shared Landing?	N/A				
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
at the second second	R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
1 Bot theme Bar	5		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
A LEAD & LEAD				X Walk 1 Direction	To N		X Walk 2 Direction	To W	
a second and a second			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name BALLANTYNE COMMONS PY				X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	5.8	
Stop Condition-Street 2 None				X Walk 1 X Slope (%)	3.7		X Walk 2 X Slope (%)	0.6	
Street 2 Name ENTRANCE			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1 StopSign				Road Slope (%)	0.6	N/A	Clear Space?	N/A	
				Road X Slope (%)	2.0	N/A	Clear Space to XWalk (in)	N/A	
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type		
					N/A			N/A	

Yes Surface Condition? (G/P)

Good

