

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Interception ID: 42744		D		Location	F			
Intersection ID: 42714	Main Street: ARBORETUM_DR		Cross Street: PROVIDENCE_RD		Location: E			
ADA ID: 47ECA3B2BBF0	A ID: 47ECA3B2BBF0 Ramp Type: MedianPerp		Initial Pass/Fail: Fail Overall Compliance			nce: N	o Severity Score:	26.25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	MY Y	Possible Solutions:	Compliance Description		Data	Data Compliance Description		Data
		Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	46.0	No	Ramp Slope (%)	13.1
	and 1		Yes	Ramp Width (in)	91.0	No	Ramp XSlope (%)	2.7
	CL* Refla	e	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	the second		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
6			N/A	Flare Traversable LT	? <b>N/A</b>	N/A	Flare Traversable RT?	N/A
ARBORETUM DR			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
AREONEDOM DR		Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	- Charles	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	<u> </u>		N/A	Shared Landing?	N/A			
		PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	3	Not Found, R304.2.2, R304.5.3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To S		X Walk 2 Direction	N/A
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE			X Walk 1 Slope (%)	1.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign			X Walk 1 X Slope (%	) 1.5		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N/A	Ramp inside XWalk1	? <b>N/A</b>	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A			Road Slope (%)	N/A	N/A	Clear Space?	N/A
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	650.00	Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

**Yes** Surface Condition? (G/P)

Good

