cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



	Main Of		0			V		Lesstiens	F	
Intersection ID: 10031811	Main Str	Main Street: MILLENNIUM_AV		reet:	POTOMAC_RIVER_P	Y		Location:	E	
ADA ID: 4859633A6B60	Ramp Ty	Initial Pass/Fail: Fail Overall Complia			nce: No Severity Score: 13.75		13.75			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:	Compliance Description		Data	Data Compliance Description		Data		
	A/NA	Remove & Replace Entire Ramp		N/A	Ramp Length (in)	56.0	N/A	Grade Break?	N/A	
				Yes	Ramp Width (in)	69.0	N/A	Grade Break Slope (%)	0.0	
	15AA		I	No	Ramp Slope (%)	9.8	N/A	Grade Break XSlope (%)	0.0	
			I	No	Ramp XSlope (%)	3.3				
			1	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
			I	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
L L L		Surveyor Notes:	I	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
L L L		N/A	I	N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
A P & Marine				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
A A A	no los	1	1	N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
A A A A A A A A A A A A A A A A A A A			1	N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	PROW/ADA:	1	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
		R304.2.2, R304.5.3	I	N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
		,	1	N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
	A. 6.		I	N/A	Painted X Walk1?	No		Road Slope (%)	3.0	
Street 1 Name	MILLENIUM AV	-			X Walk 1 Direction	To SW		Road X Slope (%)	1.7	
Stop Condition-Street 1	None				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	3.0	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	1.7	N/A	Storm Grate/Utility Hazard?	N/A	
			I	N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	0.5	
							•	• • • •		

