## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Internetion ID: 07700 Main Street: DI AKENEY, USATU DD				Owner Official DOVANT FADMO DD				Lesstian	05	
Intersection ID: 27766	27766 Main Street: BLAKENEY_HEATH_RD			Cross Street: BRYANT_FARMS_RD				Location:	SE	
ADA ID: 485F03E273B6 Ramp Type: Perp			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description			Data Compliance Description			
	strain a survey	Remove & Replace Entire Ram	).	N/A	Ramp Length (in)	37.0	No	Ramp Slope (%)	8.4	
8 mill s state	10-1-1			Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.8	
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	16			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
A A A A A A A A A A A A A A A A A A A	1 h	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
ENTER E		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	1. A. A. A.			N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
A SA PARA		Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
and the second sec				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	1.4				X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name BLAKENEY H	IEATH RD	_			X Walk 1 Slope (%)	5.2		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

Yes Surface Condition? (G/P)

Good

