

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

9.3

1.9

N/A

N/A

N/A

Intersection ID: 10040204 Main Street: TYVOLA\_RD Cross Street: N/A Location: SE

ADA ID: 48674F992627 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Flare Traversable LT?

Flare Type LT

N/A

No

N/A

N/A

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Yes

N/A

N/A

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

Flare Traversable RT?

Data

58.0

43.0

N/A

N/A

N/A



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

TYVOLA RD None ENTRANCE StopSign Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2

Total Cost:



3200.00



