


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 10020383	Main Street: BALLANTYNE COUNTRY CLUB DR	Cross Street: N/A	Location: S
ADA ID: 487EE84E1784	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	
Severity Score: 12.5			

	<p>Possible Solutions:</p> <p><b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.</b></p> <p>Surveyor Notes:</p> <p><b>N/A</b></p> <p>PROW/ADA:</p> <p><b>Not Found, R304.2.2</b></p>			
		Compliance	Description	Data
<p>Street 1 Name</p> <p>ENTRANCE</p> <p>Stop Condition-Street 2</p> <p>StopSign</p> <p>Street 2 Name</p> <p>BALLANTYNE COUNTRY CLUB DR</p> <p>Stop Condition-Street 1</p> <p>None</p>	<p>Total Cost:</p> <p>\$ 3200.00</p>	N/A	Ramp Length (in)	176.0
		Yes	Ramp Width (in)	48.0
		N/A	Flare Type LT	N/A
		N/A	Flare Slope LT (%)	N/A
		N/A	Flare Traversable LT?	N/A
		N/A	Landing Length (in)	N/A
		N/A	Landing Width (in)	N/A
		N/A	Landing Slope (%)	N/A
		N/A	Landing X Slope (%)	N/A
		N/A	Landing Curb? (Y/N)	N/A
		N/A	Shared Landing?	N/A
		N/A	Gutter Ponding?	N/A
		N/A	Gutter Lip Ht (in)	N/A
		N/A	Painted X Walk1?	No
			X Walk 1 Direction	To NE
		N/A	X Walk 1 Width (in)	N/A
			X Walk 1 Slope (%)	1.1
			X Walk 1 X Slope (%)	0.1
		N/A	Ramp inside XWalk1?	N/A
			Road Slope (%)	0.8
			Road X Slope (%)	0.4
		N/A	Any Obstructions?	N/A
			Obstruction Type	
		N/A		N/A
		Yes	Surface Condition? (G/P)	Good

