

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 46373 Main Street: HONOR_GUARD_AV Cross Street: ROYAL_CASTLE_CT Location: NW
ADA ID: 4892127E9F54 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

HONOR GUARD AV
StopSign
ROYAL CASTLE CT
None

Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:
N/A

PROW/ADA:
R304.5.1

Total Cost: \$ 3200.00

| Field Measurements/Component Compliance Compliance Description Data Compliance Description Data | | | | | | |
|--|------------------------|------|------|--------|-----------------------|------|
| Comp | Compliance Description | | Comp | liance | Description | Data |
| N/A | Ramp Length (in) | 47.0 | Yes | Ramp | Slope (%) | 5.3 |
| No | Ramp Width (in) | 43.0 | Yes | Ramp | XSlope (%) | 1.2 |
| N/A | Flare Type LT | N/A | N/A | Flare | Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare | Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | N/A | N/A | Flare | Traversable RT? | N/A |
| N/A | Landing Length (in) | N/A | N/A | DWS | Provided? | N/A |
| N/A | Landing Width (in) | N/A | N/A | DWS | Contrast? | N/A |
| N/A | Landing Slope (%) | N/A | N/A | DWS | Length (in) | N/A |
| N/A | Landing X Slope (%) | N/A | N/A | DWS | Full Width? | N/A |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS | Offset (in) | N/A |
| N/A | Shared Landing? | N/A | | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutte | r Slope (%) | N/A |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutte | r X Slope (%) | N/A |
| N/A | Painted X Walk1? | No | N/A | Painte | ed X Walk2? | No |
| | X Walk 1 Direction | To S | | X Wa | lk 2 Direction | To E |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Wa | lk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 1.4 | | X Wa | lk 2 Slope (%) | 3.8 |
| | X Walk 1 X Slope (%) | 0.3 | | X Wa | lk 2 X Slope (%) | 1.7 |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp | inside XWalk2? | N/A |
| | Road Slope (%) | 1.4 | N/A | Clear | Space? | N/A |
| | Road X Slope (%) | 2.6 | N/A | Clear | Space to XWalk (in) | N/A |
| N/A | Any Obstructions? | N/A | N/A | Storm | Grate/Utility Hazard? | N/A |
| | Obstruction Type | | | Storm | Grate/Utility Type | |
| | | N/A | | | | N/A |
| | | | Yes | Surfa | ce Condition? (G/P) | Good |
| | | | - | | | |





