

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

1.0

68.0

6.0

0.5

3.2

1.0

N/A

Cross Street: CALDWELL RIDGE PY Intersection ID: 31553 Main Street: CALDWELL RD Location: SE Initial Pass/Fail: Fail **Overall Compliance: No ADA ID: 48A16CEDDA97** Ramp Type: Combination2 **Severity Score:** 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

Yes

Yes

Yes

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

Flare Traversable RT?

Flare Type RT

Ramp XSlope RT (%)

Data

56.0

59.0

1.6

1.8

72.0

47.0

N/A

No

To NE



StopSign Street 1 Name **CALDWELL RIDGE PY** Stop Condition-Street 1 Street 2 Name N/A Stop Condition-Street 2 N/A Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: LT RP < 5% PROW/ADA: Not Found, R304.5.1

Total Cost:





		X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	3.6		X Walk 2 Slope (%)	N/A
		X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)	N/A
1600.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	N/A		Clear Space?	N/A
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A	
name of the second					Obstruction Type	
						N/A
				N/A	Storm Grate/Utility Hazard?	N/A
				İ	Storm Grate/Utility Type	
	1					N/A
	1			Yes	Surface Condition? (G/P)	Good
					Curb Slope (%)	18.9



