

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 46369 Main Street: DIXIE_HILLS_DR		Cross Street: ROYAL_CASTLE_CT			Location:	S								
ADA ID: 48E5CB55FD1D Ramp Type: Perp		Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	33.75								
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance												
	Possible Solutions:	Compliance Description Data		Data	Compliance Description		Data							
	Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	8.5							
	······	No	Ramp Width (in)	42.5	No	Ramp XSlope (%)	5.8							
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A							
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A							
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A							
Roma & Comment		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A							
E LUCASULE	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A							
	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A							
and the of the		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A							
A I I MANA		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A							
The second second		N/A	Shared Landing?	N/A										
	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A							
ALL ALL ALL ALL ALL ALL	Not Found, R304.5.1, R304.2.2,	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A							
R304.5.3		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A							
			X Walk 1 Direction	To NE		X Walk 2 Direction	N/A							
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A							
Street 1 Name ROYAL CASTLE CT			X Walk 1 Slope (%)	2.5		X Walk 2 Slope (%)	N/A							
Stop Condition-Street 2 None			X Walk 1 X Slope (%)	7.8		X Walk 2 X Slope (%)	N/A							
Street 2 Name N/A		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A							
Stop Condition-Street 1 N/A			Road Slope (%)	N/A	N/A	Clear Space?	N/A							
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A							
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A							
	Total Cost: \$ 18	850.00	Obstruction Type			Storm Grate/Utility Type								
			<i></i>	N/A		, ,,	N/A							

Yes Surface Condition? (G/P)

Good

