## 

## **Access Compliance Report** Public Rights-of-Way (Curb Ramps)



Intersection ID: 8925 Main Street: E_W_T_HARRIS_BV					Street:	THE_PLAZA	Location:	NE			
ADA ID: 48F097653520	Ramp Ty	mp Type: Combination1			Initial Pass/Fail: Fail Overall Complia			nce: N	o Severity Score:	18.75	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	· Aller Aller	Possible Solutions:			Compliance Description			Data Compliance Description			
Do ff C	The second	Remove & Replac	e Entire Ramp		N/A	Ramp Length LT (in)	98.0	N/A	Ramp Length RT (in)	100.0	
	0 4				No	Ramp Width LT (in)	34.0	Yes	Ramp Width RT (in)	59.0	
					Yes	Ramp Slope LT (%)	3.7	Yes	Ramp Slope RT (%)	7.8	
					No	Ramp XSlope LT (%)	3.0	No	Ramp XSlope RT (%)	3.3	
					N/A	Ramp Length (in)	25.5	Yes	Ramp Slope (%)	3.2	
					No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	0.5	
		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	A	LT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	t t				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	STORE (10)				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
THE PLAZA	<i>F</i> +				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
E		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	THE PARTY	Not Found, R304.	5.1, R304.5.1,		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
6.		R304.5.3	, , ,		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
					N/A	Shared Landing?	N/A				
- TITICA	andread and a second				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	YieldSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	THE PLAZA				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	113.0		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	1.0		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	1.9		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$1	800.00	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					A = 1	Lange State Lit + -		N/A	Any Obstruction?	N/A	
A DECEMBER OF THE OWNER OWNER OF THE OWNER OWNE OWNER OWNE									Obstruction Type		
										N/A	
			10	F	_	1		N/A	Storm Grate/Utility Hazard?	N/A	
		1	Mar and A		DESIGNATION AND A STATE				Storm Grate/Utility Type	11/2	
	1-11.	the second second		1 /		- / -				N/A	

N/A Surface Condition? (G/P) Good Curb Slope (%) 17.2

Yes





